

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

RECEIVED

FEB 16 2000

DIVISION OF  
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-99 To (mo./yr.) 12-31-99
2. DOGM File Number (Mine No): 513 10001
3. Mine Name: Wesco
4. Mineral(s) Mined (or permitted to mine): Sandstone
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
1/4, SE 1/4, SW 1/4, Section 35, Township 11S., Range 10E.  
SE 1/4, SW 1/4, SW 1/4, Section 35, Township 11S., Range 10E.  
1/4, 1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Quality Building Stone, Inc.
8. Permanent Street Address: 8809 S. 700W.  
City, State, Zip: Sandy, Utah 84070  
Phone: (801) 255-2911 Fax: \_\_\_\_\_
9. Company Representative (or designated operator):  
Name: Wes Hansen  
Title: Production Manager  
Business Address: 8809 S. 700W.  
City, State, Zip: Sandy, Utah 84070  
Phone: (801) 255-2911 Fax: \_\_\_\_\_  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☐ No ☒
2. If no - what was the last year of activity? Several years back - check your records.
3. If yes - how much ore or mineral was mined? - None -

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

None

5. How much **additional acreage** was disturbed during the past year? None

6. How much acreage was **reclaimed** during the past year? All

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Project area was re-seeded in November 1999,  
and the project entrance was blocked off.

8. What is the **total disturbed acreage of entire project** at years end? Reclaimed

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

This project is completed

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print): Wes Hansen

Title of Operator: Project Manager

Signature of Operator: *Wes Hansen*

Date: 2/16/2000